

TEST REPORT

Test Report # 17H-006238 Date of Report Issue: August 4, 2017
Date of Sample Received: July 31, 2017 Pages: Page 1 of 5

CLIENT INFORMATION:

Company: BIC Graphic

Recipient: 14421 Myerlake Circle

Clearwater Florida 33760

United States (USA)

SAMPLE INFORMATION:

Description: 3-in-1 Auto COB Emergency Tool (breaker component only)

Assortment: - Purchase Order Number: 1544
Item No.: 21214 Country of Origin: China

termine.

Country of Distribution: United States, Canada Labeled Age Grade: Quantity Submitted: 1 pc per style Recommended Age Grade: -

07/31/2017 - 08/04/2017

OVERALL RESULT:

Testing Period:

Refer to Detailed Results

Refer to page 2 for test result summary and appropriate notes.

ANSECO GROUP (HK) LIMITED

Tested Age Grade:

Ricky Cheung Chin Yeung Manager, Physical Laboratory

ANSECO GROUP (HK) LIMITED • 3/F Liven House • No. 61 – 63 King Yip Street • Kwun Tong • Kowloon • Hong Kong • Tel: (852)3185 8000

The test result(s) and conclusion(s) in this report relate only to the sample(s) tested as described herein.

This test report may not be reproduced except in full, without written approval of ANSECO GROUP (HK) LIMITED.



Test Report # 17H-006238 Pages: Page 2 of 5

TEST RESULTS SUMMARY:

At the request of the client, the following tests were conducted:

CONCLUSION	TEST(S) CONDUCTED
Refer to Detailed Results	Client Requirement – Performance Test



Test Report # 17H-006238 Pages: Page 3 of 5

DETAILED RESULTS:


Client Requirement – Performance Test

Test	Result	Conclusion
In-house method: Use the product to break a car door window.	The door window was broken at the first hit. (See the P01 and P02)	INFORMATION ONLY



Test Report # 17H-006238 Pages: Page 4 of 5

TEST PHOTO:



P01 (Before Test)



P02 (After Test)

ANSECO GROUP (HK) LIMITED • 3/F Liven House • No. 61 – 63 King Yip Street • Kwun Tong • Kowloon • Hong Kong • Tel: (852)3185 8000



Test Report # 17H-006238 Pages: Page 5 of 5

SAMPLE PHOTO:



-End Report-